


Measurement at Work Site

Investigate skin vascular damage caused by use of aggressive chemicals or vibrating tools


Step 1. Place hand below camera on *TiVi60 Skin Damage Visualizer* platform.



Step 2. Map skin irritation (contact dermatitis)

or...


... vibrational damage (white fingers).



Step 3. Use Library or Trend Monitor to analyze changes over time.

WheelsBridge

PIONEERS IN TISSUE VIABILITY IMAGING



WheelsBridge AB, Lövsbergsvägen 13, S-589 37 Linköping, Sweden
Phone: +46-708-765-190, E-mail: info@wheelsbridge.se, WEB-site: www.wheelsbridge.se